

SHIP REPAIR DIVISION

M/V HARRIER EXPLORER



Main particulars

 Type:
 RESEARCH SURVEY VESSEL

 IMO:
 7807380

 LOA x B:
 81,26 x 18,30 m

 GRT:
 4.009

 DWT:
 2.477

 Flag:
 PANAMA

 R.Owner:
 HARRIER NAVIGATION (CYPRUS)

 T.Manager:
 SEA BIRD EXPLORATION (CYPRUS)

 Operator:
 SEA BIRD EXPLORATION (CYPRUS)

 Arrival:
 18/02/2017

 Departure:
 04/03/2017

SHIP REPAIR REPORT

Reference: RE01703

SCOPE OF WORKS CARRIED OUT

- * Docking, undocking and provision of general services for repair works.
- Hull treatment works: HP washing, hand scrapping, blasting SA 2 in spots, application of touch up coats on blasted areas, application of 2 full coats, repainting of marks and letters.
- Treatment works on sea chest
- * Renewal of anodes
- Repair cavitations of propeller blades
- * Propellers polishings
- * Thickness measurements
- * Rudder. Remove and refit, pressure test, renew rudder stock packing, rudder measurements.
- * Overhauling of valves
- * HP Water cleaning of two fresh water tanks
- * Load test of full set of cranes, gangways and davits.
- * Anchor and chains. HP washing, calibration, painting
- * Renewal of anchor chain lenght (18 units) and 18 kenter shackle
- * Chain lockers steel repairs. Renewal longitudinal bulkheads and reinforcement of bottom plate. Cleaning of chain lockers.
- * Minor steel repairs on ballast tanks.
- * Cleaning of Main and Emergency Switchboards and Breakers; retightening of connections.
- * Removal and refitting of tail shaft for inspection and further maintenance works.
- * Pressure test of safety valves of starting air bottles
- * Cleaning and refit of four (4) Air Coolers.