

M/V ATLANTIC CHALLENGE



Main particulars

Type: STERN TRAWLER

IMO: 9213442

LOA x B : 59 x 14,50

GRT: 1.783

DWT:

Flag: Irish Republic

R.Owner: KILLYBEGS FISHING (Irish Republic)

T.Manager: KILLYBEGS FISHING (Irish Republic)

Operator: KILLYBEGS FISHING (Irish Republic)

Arrival: 31/07/2017

Departure: 04/09/2017

SHIP REPAIR REPORT

Reference: RE01713

SCOPE OF WORKS CARRIED OUT

- * Docking, undocking and provision of general services for repair works.
- * **Hull treatment works:** HP washing, machine brushing on top side areas followed by a roller touch up; slurry blasting SA 2 on flat bottom and vertical sides. Painting FB and VS with three coats, repainting of hull marks.
- * Painting of all the surfaces already painted in cream color (from Main Deck upwards)
- * Painting of TRANSOM
- * Painting of External Decks already painted in green.
- * Repair of corrugated transverse bulkhead between tanks 1 & 2 starboard.
- * Painting of affected RSW tanks n° 1 and 2 on starboard side after steel renewal on corrugated transversal bulkhead.
- * Renewal of anodes
- * Overhauling of valves. Removal and machining of valves.
- * Tailshaft poker measurement
- * Rudder stock, flap and pintle measurement.
- * Main propeller and aft and bow thruster propeller polishing.
- * Cleaning and painting of mud boxes.
- * Cleaning and painting of seachests and seachest grids.
- * Renewal of harbour generator radiator.
- * Modification of the grids of the hatchcovers of RSW tanks.
- * Repair of some windows of the wheelhouse
- * Anchors painting in situ with one paint coat.
- * Repair the deck crane cylinder