

SHIP REPAIR DIVISION

M/V SUAR VIGO



Main particulars

Type: CAR CARRIER IMO: 9250000

LOA x B: 149,38 x 21,44

GRT: 16.361 **DWT:** 4.500 **Flag:** Spain

R.Owner: FLOTA SUARDIAZ S.L. (SPAIN)
T.Manager: FLOTA SUARDIAZ S.L. (SPAIN)
Operator: FLOTA SUARDIAZ S.L. (SPAIN)

Arrival: 17/08/2017 **Departure:** 21/08/2017

SHIP REPAIR REPORT

Reference: RE01715

SCOPE OF WORKS CARRIED OUT

- * Docking, undocking and provision of general services for repair works.
- * **Hull treatment works:** HP washing of flat bottom, vertical sides and top sides.
- * Desoxidation of hull areas with Minea Ferronet.
- * Painting of hull marks, names and symbols.
- * Cleaning and painting of seachests and seachest grids.
- * Main work: Substitution of starboard propeller hub by new one provided by owner.
- * Erection and removal of stagings
- * Dismounting and mounting back the rope guard of starboard shaft.
- * Dismounting and mounting back the starboard propeller blades.
- * Draining of starboard propeller hub.
- * Assistance to Rolls Royce technician in the dismounting works of starboard propeller and installation of new propeller hub.
- * Rectified of the roots of propeller blades.
- * Dye penetration test on starboard propeller
- * Maintenance works on bowthruster propeller