

M/V BOUZAS



Main particulars

Type: CAR CARRIER

IMO: 9249996

LOA x B : 141,25 x 21,44

GRT: 15.224

DWT: 4.695

Flag: Spain

R.Owner: FLOTA SUARDIAZ S.L. (SPAIN)

T.Manager: FLOTA SUARDIAZ S.L. (SPAIN)

Operator: FLOTA SUARDIAZ S.L. (SPAIN)

Arrival: 08/08/2017

Departure: 14/08/2017

SHIP REPAIR REPORT

Reference: RE01714

SCOPE OF WORKS CARRIED OUT

- * Docking, undocking and provision of general services for repair works.
- * **Hull treatment works:** HP washing of flat bottom, vertical sides and top sides. Application of one full coat of silicon paint on flat bottom and vertical bottoms.
Application of one touch up coat on top sides by roller.
- * Painting of hull marks, names and symbols.
- * Painting of forward owner emblem.
- * HP washing and application of three coats on aft ramp.
- * Renewal of anodes
- * Anchor and chains. Lowering, HP washing, calibration, painting
- * Tailshaft poker measurement
- * Assistance to the appointed technician in the vulcanizing works of stern tube seals.
- * Dismounting and mounting of propeller blades.
- * Rudder stock measurements.
- * Assistance to Rolls Royce technician in the dismounting works of bowthruster propeller, transport to our mechanical workshop, disassembling, changing of worn-out elements, reassembling and fitting on board on its place.
- * Overhauling of valves. Removal and machining of valves.
- * Dye penetration test on main and bow thruster propeller.
- * Cleaning and painting of seachests and seachest grids.