

SHIP REPAIR DIVISION

M/V BOW OCEANIC



Main Particulars

Type: CHEMICAL TANKER IMO: 9143121 LOA x B: 142 x 23 m GRT: 10.369 DWT: 17.460 Flag: Brazil R.Owner: ODFJELL CHEMICAL TANKERS AS (NORWAY) T.Manager: FLUMAR TRANSPORTES DE QUIMICOS (BRAZIL) Operator: FLUMAR TRANSPORTES DE QUIMICOS (BRAZIL) Arrival: 22/01/2015 Departure: 10/02/2015

SHIP REPAIR REPORT

SCOPE OF WORKS CARRIED OUT Reference: RE01502

- Docking / undocking and provision of general services for repair works Major piping works (some Cunifer)
- Hull treatment works: HP washing of underwater area and top sides areas.
 Application of 3 TU coats on flat bottom and 1 FC.
 Application of 3 TU coats on vertical bottom + 2 FC.
 Application of 4 TU coats on ten sides
- Application of 4 TU coats on top sides
- Painting of marks, names, draft scales, boundary marks betweeb tanks boundary lines
- * Painting of exhaust pipes
- * Anchor and chains: Lower anchor and chains, cable marking and calibration; anchor and chains cleaning; cleaning and painting of chain lockers.
- * Cleaning of four HFO tanks.
- * Renewal of aluminim anodes on external shell
- * Allowed for 500 m of conduit pipe replacement for cargo monitoring system
- * Major steel repairs on Chain Locker, Water Ballast and HFO tanks
- * Repair of pittings on ballast tanks
- * Cracks welding on Main Steam Line
- * Repair of deck railings and ropeguard
- * Overhauling of Main Engine
- * Propeller repair and polishing
- * Stern tube seals renewal
- * Removal of CPP cooler
- * Repair damage in gearbox
- * Removal and repair of Shaft Generator
- * Overhauling of Alternator and Circuit Breakers
- * Overhauling of PV valves