

# SHIP REPAIR DIVISION

# M/V AS FABIANA



#### **Main Particulars**

**Type:** CONTAINER SHIP

**IMO:** 9395109

**LOA x B:** 166,15 x 25,00

**GRT:** 15.375 **DWT:** 18.278 **Flag:** Portugal

**R.Owner:** AS Fabiana mbH & Co KG (Germany)

**T.Manager:** Ahrenkiel Steamship GmbH & Co (Germany) **Operator:** Seatrade Reefer Chartering NV (Belgium)

**Arrival:** 12/09/2016 **Departure:** 07/10/2016

### **SHIP REPAIR REPORT**

### SCOPE OF WORKS CARRIED OUT Reference: RE01616

- \* Docking / undocking and provision of general services for repair works.
- \* Full blasting SA -2 of hull (underwater area + top sides).
- Painting works.
- \* Renewal of cathodic protection.
- \* Cleaning of HFO tanks.
- \* Polishing of propellers.
- \* Bow thruster overhauling and repairs. Polishing of blades.
- \* Overhauling of ship's valves.
- \* Cargo cranes testing.
- \* Removal and cleaning of M/E heater.
- \* Hatch covers: Remove rubber, renew lashing pad eyes, renew rubber channels, replace of single sockets.
- \* Major steel renewal on bulb and hull.
- Steel renewal on two wing tanks.
- \* Forecastle steel reinforcement.
- \* Removal of existing ducts, fabrication and installation of new cargo hold ventilation ducts.
- \* Overhauling of auxiliary engines.
- \* Overhauling of A/E turbocharger.
- Overhauling of A/E air cooler.
- \* Removal of gratings, fabrication and installation of new ventilation gratings.
- Installation of new lub oil pumps.
- \* Renewal of some sea water coolers pipe.
- \* Overhauling of some electric coolers.
- \* Boiler outfitting overhaul. Boiler safety valves.
- \* Ultrasonic cleaning and pressure testing of ME FO Heat Exchanger.